BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

	Name Of Work:	Providing and laying HDPE water line in Brindavana nagara Block 1 in JP Park ward 17
2	Administration Approval & Date	JC/RRN/AS/2260/2013-14 Dtd: 17.09.2013
3	Technical Sanction Estimate No. & Date	CE/RRN/TS/307/2013-14 Dtd: 18.09.2013
4	Estimate Amount	49,94,000/-
5	Job Code No.	017-14-000028
6	P-Code	P-2201
7	Agreement No and Date:	EE/RRND/Agmt/217/13-14 Dtd: 05.02.2014
8	Work order Number & Date	EE/RRND/WO/217/13-14 Dtd: 05.02.2014
9	Contract Amount as per Agreement	Rs. 53,42,328/-
10	Bill Amount	Rs. 46,57,223=11
1	B.R No. & Date	244/14-15 Dtd: 30.06.2014
2	Agency	G Vasu
3	M.B. Number & Page No. of Measurement records	83/12-13 Page No 8265 to 8271
4	Date of Inspection	01.09.2017
	Enclosures	4 Number of photos taken during inspection

The above site Location has been Inspected by me along with the Consarned person, as per EE (RRND) Letter no EE/RRN/PR/414/A 17-18 Dated 1-9-2017. It is observed that most of the Items indi -cated in the Xerox Copy of MB/X & Sheets are not susceptible for Inspection Report measurements, as the nature of work is Laying of HDP water Line, as such the photos taken during the execution of work have been scrutinized and Inspected, it appears that the abo work has been done. The Items which are susceptible for measurements have been checked and found to be Satisfactor This has a reference to the NOC Issued by Lokayukta Vide Letter no LOK/INV(J)/CT/Crime 60/2014 Dated 1-8-2017

1/9/2017

(R. Sathyanarayana)
Inspection Report Officer.

EE (RRN) Division, JR Nagara Zone.

R. SATHYANARAYANA
INSPECTION OFFICER

Scanned by CamScanner